

### WARNING:

**Remove batteries before heat molding.** (Batteries are located inside liner cuff.)



### Therm-ic Liner Quick Start Guide:


#### Batteries will need to be connected before use:

Battery connector is protected with black tape, remove the black tape. Liner connector could be covered by liner fabric. Join red connectors.



#### How to charge batteries

Attach USB cable to charging cable on medial side of liner. Align white marks on cables. Thermic logo will be green when charging is complete.




#### How to adjust heat setting

Button should be pressed for 1-2 seconds to change heat setting.

#### Specifications:

Heating time  
 Setting 1: 14 to 17.5 hours  
 Setting 2: 7 to 8.5 hours  
 Setting 3: 3.5 to 4.5 hours  
 Charging time: 6 to 7 hours



### Traveling with Lithium Ion Batteries:

Due to ever changing regulations surrounding flying with lithium ion batteries, we are unable to approve or disapprove flying with lithium ion batteries. Each airline may have slightly different regulations. Check with your airline before departure

#### Battery info:

CE certified rechargeable lithium ion battery  
 3.7V, 2600mAh, 9.62Wh  
 Size: 52.2mm x 34.2mm x 16.0mm